

Vehicle Condition Report:

Vehicle Information:

Vehicle Type: Transit Buss

Other: _____

Unit No: 98186

Year: 2018

Make: Gillig

Model: Low Floor Bus

VIN/SN: 15GGE2712J3093249

Miles: 129835

Engine Information:

Year: _____

Make: Cummins

Model: _____

SN: _____

Fuel Type: Diesel

Vehicle Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: _____

Exterior Condition: _____

Condition Comments: _____

Engine Displacement: 8.9 Liters. Crankshaft (V, Inline, Boxer) _____

Cylinders: _____

Power Windows: No

Power Locks: Could not confirm

Air Conditioner / Heat: Yes

AC / Heat Functional: Could not confirm

Transmission: Automatic

Number of Manual Speeds: _____

Unit Moves FWD/REV: Both

Four Wheel Drive (4x4): No

Functional: N/A

Additional Equipment: _____

Chassis:

Suspension: Air

Notes: _____

Wheelbase: _____

GVWR: 34500

Front: 11000

Rear(s): 23500

Tire Size: _____

Front: 275/70R22.5 J

Rear: _____

Comments: _____

Cargo / Passenger Vans

Passenger Van Seating: 28 Rows

Cargo Van Box Dimensions:

Length: _____

Width: _____

Height: _____

Additional Notes: _____