Vehicle Condition Report:

Vahiala Tura	VE	nicle inform	iation.				
Vehicle Type:	Cala a al Dona						
•	School Bus		F., .:				
Unit No: 9747			_	ne Inforn	nation:		
Year: 2012		Year:	2011				
Make: Freightliner		Make:	Cummins				
Model: B2 Bus		Model:	ISB				
VIN/SN: 4UZABRDT1CCBN9	9747	SN:					
Miles: 861995		Fuel Type:	Diesel				
		ehicle Cond					
Mechanical Condition:		<u> </u>	is in need of rep	oair.			
Interior Condition:		•					
Exterior Condition:	Fair - Visible dents an	d scratches					
Condition Comments:							
Engine Displacement:	6.7 Liters. C r	ankshaft (V.	Inline, Boxer)			Cylinders:	6
Power Windows:	No		Power Locks:	No			
Air Conditioner / Heat:	Could not confirm	AC / Heat	Functional:	.,,,			
Transmission:	Automatic		ber of Manual	Sneeds:			
Unit Moves FWD/REV:	Neither	, italii	bei oi ivialidai	opecus.			
Four Wheel Drive (4x4):	No		Functional:				
Additional Equipment:	NO		runctional.				
Additional Equipment.							
-							
		Chassis					
Suspension:	Carina	Notes:					
Wheelbase:	Spring	-	21000	Front:	10000	Poor(s).	21000
Tire Size:		·	31000	-		Rear(s):	21000
	Front:	11R22.5		Rear:	11R22.5		
Comments:							
Cargo / Passenger Vans							
Passenger Van Seating:	Rows	12					
Cargo Van Box Dimensions:	Length:		Width:		Height:		
Additional Notes:			_				
•							
			-		-		