

Boom Truck Condition Report:

Equipment Information:

Unit No: _____ Engine Information:
Year: 1999 Year: _____
Make: MACK Make: MACK HP: 300
Model: MR688P Model: 300 HP
VIN/SN: 1M2K194COXMO13618 SN: _____
Miles/Hrs.: 148535/5194 Fuel Type: Diesel

Equipment Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.
Interior Condition: Fair - Interior is heavily worn.
Exterior Condition: Fair - Visible dents and scratches
AC/Heat Functional: Yes
Leaks Present: Not Seen Engine Displacement: 12 Number of Cylinders 6
Sleeper (if Applicable): Length: _____ # of Bunks: _____ Aux Power Unit? _____
Additional Equipment: _____

Transmission:

Transmission Make: MACK
Auto / Manual: Automatic Number of Speeds: _____
Truck Moves FWD/REV: Both
Comments: _____

Chassis:

Frame Rails: _____ Notes: _____
Suspension: Spring Notes: _____
Wheel Base: _____ in. _____
Axle Weight Ratings (LBS): GVWR: _____ Front Axel: _____ Rear(s): _____
Tire Size: Front: 11R22.5H Rear(s): 11R22.5H
Comments: _____

Flatbed

Bed Dimensions: Length: 20 ft. Width: 102" ft.
Conveyor/Boom Make: _____ Conveyor/Boom Model: _____
Conveyor/Boom Is Functional: _____

Additional Notes: