

# Heavy Equipment Condition Report:

## Asset Information:

Equipment Type: \_\_\_\_\_

Other: Snow Plow

Unit No: \_\_\_\_\_

Year: \_\_\_\_\_

Make: Harlan

Model: \_\_\_\_\_

VIN/SN: \_\_\_\_\_

Miles/Hrs.: 1489

Engine Information:

Year: \_\_\_\_\_

Make: \_\_\_\_\_

Model: \_\_\_\_\_ HP: \_\_\_\_\_

SN: \_\_\_\_\_

Fuel Type: \_\_\_\_\_

## Asset Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Good - Damage is limited to normal wear and minor scratches.

Exterior Condition: Good - Minor dings and scratches

Hydraulics are Functional: Yes

Hydraulic Leaks Present: No

Unit Moves FWD/REV: Both

All Attachments Articulate

Notes: \_\_\_\_\_

Control Station Type: None

AC/Heat: \_\_\_\_\_ AC/Heat working: \_\_\_\_\_

Additional Equipment: \_\_\_\_\_

## Chassis:

Powertrain Type: \_\_\_\_\_

Propulsion Type: \_\_\_\_\_

Track Condition: \_\_\_\_\_

Wheel Condition: Good - Wheel condition shows normal wear from use

Tire Size: Front: \_\_\_\_\_

Rear(s): \_\_\_\_\_

## Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: \_\_\_\_\_

Type: \_\_\_\_\_

Details: \_\_\_\_\_

Type: \_\_\_\_\_

Details: \_\_\_\_\_

## Additional Notes: