

Truck Tractor Condition Report:

Equipment Information:

| | | | |
|----------|-------------------|---------------------|-------------|
| Unit No: | 226582 | Engine Information: | |
| Year: | 2004 | Year: | 2004 |
| Make: | Freightliner | Make: | Caterpillar |
| Model: | M2 106 | Model: | Cat C7 |
| VIN/SN: | 1FVACWDC64HN31220 | SN: | |
| KM/Hrs.: | 270817 | Fuel Type: | Diesel |

Equipment Condition:

| | | | |
|--------------------------|--|----------------------|-----|
| Mechanical Condition: | Good - Starts and operates; Some parts may require repair or replacement soon. | | |
| Interior Condition: | Fair - Interior is heavily worn. | | |
| Exterior Condition: | Fair - Visible dents and scratches | | |
| AC/Heat Functional: | Yes | | |
| Leaks Present: | Not Seen | Engine Displacement: | 7.2 |
| Sleeper (if Applicable): | Length: | # of Bunks: | |
| Additional Equipment: | | Number of Cylinders | 6 |
| | | Aux Power Unit? | |

Transmission:

| | | |
|----------------------|--|-------------------|
| Transmission Make: | | |
| Auto / Manual: | Automatic | Number of Speeds: |
| Truck Moves FWD/REV: | Both | |
| Comments: | box truck has a leak that has caused some damage to the wood deck. | |

Chassis:

| | | | |
|----------------------------|------------|----------|-------------|
| Frame Rails: | Double | Notes: | |
| Suspension: | Spring | Notes: | |
| Wheel Base: | | in. | |
| Axle Weight Ratings (LBS): | GVWR: | 26,000 | Front Axel: |
| | | 8,000 | Rear(s): |
| | Tire Size: | Front: | 11R22.5 |
| | | Rear(s): | 11R22.5 |
| Comments: | | | |

Specialized Equipment:

| | | | |
|--------|--|----------|--|
| Type: | | Details: | |
| Type: | | Details: | |
| Notes: | | | |
| Notes: | | | |