## **Truck Tractor Condition Report:**

			Equip	ment Infor	mation:			
Unit No:	235352			_	Engine Information:			
Year:	2016			Year:	2016			
Make:	Freightliner			Make:	Cummins			
Model:	M2 106			Model:	ISB		HP:	
VIN/SN:	3ALACWDT0GD	HF0179		SN:	4345171			
KM/Hrs.:	341086/9773			Fuel Type:	Diesel			
			Equi	pment Con	dition:			
Mechan	ical Condition:		Fair - Starts and operates but some parts require repair or replacement.					
Inte	rior Condition:	Fair - Interior is heavily wor						heavily worn.
Exte	rior Condition:					F	air - Visible dents	and scratches
AC/H	eat Functional:	Yes						
	<b>Leaks Present:</b>	Fuel Engine Displaceme		isplacement:	6.7	Number of Cylinders 6		6
Sleeper (if Applicable):		Length:	gth: # of Bunks: A		Aux	Power Unit?		
Addition	nal Equipment:							_
			•	Transmissic	n:			
Trans	mission Make:							
Auto / Manual:		Automatic			Number of Speeds:			
Truck Mo	ves FWD/REV:	Both						
	Comments:	Has fuel leak, box needs work on outside and floor inside has plywood down to cover ho						
				Chassis:				
	France Deiler			Cilassis.		Makas		
Frame Rails:		Consider			Notes:			
	Suspension:	Spring		:		Notes:		
Avla Wajahi	Wheel Base: t Ratings (LBS):	GVWR:	26,000	in. Front Axel:	9 000		<b>Poor(s):</b> 10.00	0
Axie weigh	Tire Size:		26,000 11R22		8,000	Rear(s):	Rear(s): 19,00 11R22.5	<u> </u>
	Comments:	Front:	11KZZ	.5		Rear(s):_	11K2Z.5	_
	comments:							
			Spaci	ialized Equi	nmont:			
Туре:			Speci	Details:	pinent.			
Type: Type:				Details:				
· , pc								
Notes:								
Notes:								
_								