Boom Truck Condition Report:

		Equip	ment Infor	matior	າ:				
Unit No: PB272555			_		Engine Info	rmation:			
Year: 2007			Year:	2007					
Make: Sterling			Make:	Cat			HP:		210
Model: Acterra			Model:	C7					
VIN/SN: 2FZACGDC87AY	⁄57290		SN:						
Miles/Hrs.:			Fuel Type:	Diesel					
Equipment Condition:									
Mechanical Condition:	Poor - W	ill not start	or operate an	d is in ne	ed of repair.				
Interior Condition:	Fair - Inte	erior is hea	vily worn.						
Exterior Condition:	Poor - M	ajor body d	lamage.						
AC/Heat Functional:	No								
Leaks Present:	Oil	Engine Di	splacement:	7.2	Numb	er of Cylind	ders	6	
Sleeper (if Applicable):	Length:	# of Bunks:		Aux	t? _				
Additional Equipment:									
Transmission:									
Transmission Make:	Eaton								
Auto / Manual:	Manual				Number o	f Speeds: _	8		
Truck Moves FWD/REV:	Neither								
Comments:									
Chassis:									
Frame Rails:	Single		CHassis.		Notes:				
Suspension:					Notes:				
Wheel Base:			in.		Notes.				
Axle Weight Ratings (LBS):		33,000	.'''· Front Axel:	10,000	<u> </u>	Rear(s):	23,000		
Tire Size:		11r22.5	_ ITOTIC AXCI	10,000	Rear(s):	11r22.5	23,000		
Comments:		11122.5				11122.3			
Commences									
			Flatbed						
Bed Dimensions:	Length:	20	ft.	Widt	h: 8	ft.			
Conveyor/Boom Make:	_		_		Boom Model:				
Conveyor/Boom Is I			_	•	-				
Additional Notes:	Unit does not run has been sitting for more than 2 years. location could not jump and our								
	jump box would not power up the unit								