Truck Tractor Condition Report:

		Equipment infori	Hation.		
Unit No: PB272309	PB272309 Engine Information:				
Year: 2007		Year:	2007		
Make: Sterling		Make:	CAT		
Model: Acterra		Model:	C7	HP:	210
VIN/SN: 2FZACFDC	37AY57563	SN:			
KM/Hrs.: 299894		Fuel Type:	Diesel		
		Equipment Con	dition:		
Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.					
Interior Condit	tion: Good - Dam	nage is limited to normal	wear and minor scrat	ches.	
Exterior Condit	Good - Min	or dings and scratches			
AC/Heat Function	onal: Yes				
Leaks Pres	ent: Not Seen	Engine Displacement:	7.2 Num k	er of Cylinders	6
Sleeper (if Applical	leeper (if Applicable): Length:		Aux	Aux Power Unit?	
Additional Equipm	ent:				
		Transmissio	n:		
Transmission M					
	Auto / Manual: Manual		Number of Speeds: 6		
Truck Moves FWD/I					
Comme	ents:				
		Chassis:			
Frame R	aile:	Citassis.	Notes:		
Wheel B		in.	Notes.		
Axle Weight Ratings (L		26,000 Front Axel:	8,000	Rear(s):	19,000
Tire !		11R22.5	Rear(s):	11R22.5	15,000
Comme	_	TINZZ.3		111122.3	
Commi					
		Specialized Equi	nment:		
Гуре:		Details:	Jili Cilci		
Гуре:		Details:			
··					
Notes:					
Notes:					
				_	