

Trailer Condition Report:

Equipment Information:

Unit No: B6328
Year: 1999
Make: Trilmobile
Model:
VIN/SN: 1PTF7ATJ1X9008114

Equipment Condition:

Mechanical Condition: Good - Some Parts May Require Repair or Replacement Soon

Interior Condition: Good - Some Parts May Require Repair or Replacement Soon

Chassis:

GVWR: 85,000 Suspension: Air
Tire Size: 11r22.5 Sliding Tandem Axle: No
Braking: Air
Comments:

Deck

Hitch Type:
Dimensions: Length: 48 Width: 96
Ramps (if equipped)

Specialized Equipment:

Type: Details:
Type: Details:
Notes:
Notes: