Vehicle Inspection Form

	Inventory ID: Asset Number: Fair Market value.	
	2500HO	
	Year Title No Title	
	VIN. 16 (HIC 731C 168 F 111165 Title: XClean Little Salvage Little Other Other	
	Odometer: 93757 Miles Kilometers Hours Odometer Accurate? Yes No Unknown	
	Long Description: This Vehicle: Starts With a Boost & Runs/Drivable Engine Runs Does Not Run For Parts Only Engine- Type: L, V Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid	
	Engine Condition: Runs Needs repair is in unknown condition	
	Repairs needed: Manifolds & Battery Days Hours Miles/Kilometers	
	This venicle was maintained every Maintenance Records: Available Not Available For Inspection	
	Transmission: Automatic Manual Speed Condition: Operable Needs repair Is Unknown Condition	
	Repairs Needed:	
	Drivetrain: 2 Wheel Drive X 4 Wheel Drive Condition:	
	Exterior: Color: Black Red Windows: No Cracked Glass Cracked	
	Minor: Dents Scratches Dings Tire Condition:Tread:#FlatHubcaps #	
	Major Damage to: Additional Damage: Wheel Well Rust on Bed. Roof Rust	
	Additional Damage: Wheel Well Was Ovinsed. Impressions Remain No impressions Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No impressions	1
	Decals: None Have Been sprayed & There are holes in the exterior There are no holes Emergency equip: None Has been removed & There are holes in the exterior There are no holes	
	Interior: Color Back Vinyl Leather	1
	Damage to Seats: 15 He Wear on Drivers Seat	1
	Damage to Dash/Floor: Holes in Console	
	Naulo: Ristoria:	
	AC Condition: Cold Unknown No AC Air Bags: Driver's Side Dual	
	Cruise Control Tilt Steering Remote Mirrors Climate Control	
	Power: Steering Windows Door Locks Seats	
	Additional Equipment:	
/	Manufacturer Model Serial #	
[Tool Box Light Bar Ladder Rack Utility Body: Brand Hitch: Type	
Location of Asset:		