Vehicle Inspection Form

Inventory ID:	Asset Number:	Fair Market Value:
Short Description: Year 200 & Make Ches	/ Model_	Silvercelo 3500
VIN: 1634/34/48E117491 Title: Salvage Title Salvage Title No Title Court Documents Only SF97 Form Other Odometer: 53082 Miles Kilometers Hours Odometer Accurate? Yes No Unknown		
Long Description: This Vehicle: Starts Starts with a Boost & Runs/Drivable Engine Runs Does Not Run For Parts Only Engine- Type: L, V S Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid Engine Condition: Runs Needs repair is in unknown condition Repairs needed:		
This vehicle was maintained every Omonths Days Hours Miles/Kilometers Date Removed from Service: Waintenance Records: Available Not Available For Inspection Transmission: Automatic Manual Speed Condition: Operable Needs repair Is Unknown Condition		
Repairs Needed: Drivetrain: 2 Wheel Drive X 4 Wheel Drive Condition:		
Exterior: Color: Color: Windows: Mo Cracked Glass Cracked Minor: Dents Scratches Dings Tire Condition: Fall Tread: #Flat Hubcaps # Major Damage to: Tread: Flat Hubcaps Tire Condition: Color: Fall Hubcaps Hubcaps Major Damage to: Tread: Flat Hubcaps Hubcaps Color: C		
Additional Damage: Bed Rusted Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No impressions Emergency equip: None Has been removed & There are holes in the exterior There are no holes		
Interior: Color Gray Cloth Vinyl Leather Damage to Seats:		
Damage to Dash/Floor: Radio: Stock or Brand & Model: AM AM/FM AM/FM Cassette AM/FM CD AC Condition: Cold Unknown No AC Air Bags: Driver's Side Dual Cruise Control Tilt Steering Remote Mirrors Climate Control Power: Steering Windows Door Locks Seats		
Additional Equipment: Lift Gate Manufacturer The Model II-15 Serial #		
Manufacturer Model Serial # Tool Box		
Location of Asset:		