

# Heavy Equipment Condition Report:

## Asset Information:

**Equipment Type:**

Other: Rear Rotating Spreader

Unit No: 18742

**Engine Information:**

Year: 2018

Year: 2018

Make: RBR

Make: Cummins

Model: Venturi 380

Model: QSL9

VIN/SN: FA1806265

HP:

Miles/Hrs.: 3499

Fuel Type: Diesel

## Asset Condition:

**Mechanical Condition:** Good - Starts and operates but some parts require repair or replacement.

**Interior Condition:** Good - Damage is limited to normal wear and minor scratches.

**Exterior Condition:** Good - Minor dings and scratches

**Hydraulics are Functional:** No

**Hydraulic Leaks Present:** \_\_\_\_\_

**Unit Moves FWD/REV:** Both

**All Attachments Articulate** No

**Notes:** \_\_\_\_\_

**Control Station Type:** Enclosed Cab

**AC/Heat:** Yes **AC/Heat working:** Yes

**Additional Equipment:** \_\_\_\_\_

## Chassis:

**Powertrain Type:** 4WD

**Propulsion Type:** Wheel, Pneumatic

**Track Condition:** \_\_\_\_\_

**Wheel Condition:** Fair - Wheel condition shows heavy use and may require maintenance

**Tire Size:** Front: 380/90R46

Rear(s): \_\_\_\_\_

## Attachments

Are there additional attachments that are not currently connected to this asset?

**Describe:** \_\_\_\_\_

Type: \_\_\_\_\_

Details: \_\_\_\_\_

Type: \_\_\_\_\_

Details: \_\_\_\_\_

## Additional Notes:

\_\_\_\_\_