Vehicle Inspection Form

Inventory ID: Asset Number: 0/82 Fair Market Value:
Short Description: Year 2014 Make DODGE Model CHARGER
VIN: 2 C 3 C D X A G Ø E H 3 6 8 2 3 8 Title Restriction: □Y □N Odometer: 1 5 6 0 2 O ⊠Miles □ Kilometers Odometer Accurate ☒Y □ N:
Long Description: This Vehicle: □ Starts □ Starts with a Boost & □ Runs/Driveable □ Engine Runs □ Does Not Run □ For Parts Only Engine- Type: 3. L, V □ □ □ Gas □ Diesel Engine □ Propane/Natural Gas □ Gas/Electric Hybrid Engine Condition: □ Runs □ Needs repair □ is in unknown condition Repairs needed: This vehicle was maintained every □ □ Days □ Hours □ Miles Date Removed From Service: 8112121
Drivetrain: □ 2 Wheel Drive □ 4 Wheel Drive Condition: □ Windows: ☒ No Cracked Glass □ Cracked □ Exterior: Color: □ White □ Windows: ☒ No Cracked Glass □ Cracked □ Minor: □ Dents □ Scratches □ Dings □ Tire Condition: ☐ Tread. ☐ #Flat □ Hubcaps #☐ Major Damage to: □ Additional Damage: □ Decals: □ None □ Have Been Sprayed or ☑ Have been Removed & ☑ Impressions Remain □ No Impressions Emergency equip: □ None □ Has been removed & □ There are holes in the exterior □ There are no holes
Interior: Color Glack Cloth Vinyl Leather Damage to Seats: DIS Toyn, Holes Damage to Dash/Floor:
Additional Equipment: Manufacturer Model Serial # Tool Box Light Bar Ladder Rack Utility Body: Brand Hitch: Type Location of Asset: For more information contact: Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.