Vehicle Inspection Form

Inventory ID:	Asset Number: 0190	Fair Market Value:
Short Description: Year 2015 Make Do	<i>₽6€</i> Model_	CHARGER
VIN: $2 \ C \ 3 \ C \ D \ X \ A \ G \ F \ H \ 7 \ 6 \ B \ 9 \ 2 \ 7$ Title Restriction: $\Box Y \ \Box N$		
Odometer: 7 7 7 3 0 Miles Kilometers Odometer Accurate XY N:		
Long Description:		
This Vehicle: Starts Starts with a Boost & Runs/Driveable Engine Runs Does Not Run For Parts Only		
Engine-Type: 2.6 L, V 6 Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid		
Engine Condition: Runs Needs repair is in unknown condition		
Repairs needed: ENGINE Cade, Driver Complaind about Shifting 1554=		
This vehicle was maintained every Days Days Miles		
Date Removed From Service: 9127124 Maintenance Records: Available Not Available For Inspection		
Transmission: ☑ Automatic ☐ ManualSpeed Condition: ☐ Operable ☐ Needs repair ☑ Is Unknown Condition		
Repairs Needed:		
<u>Drivetrain</u> : 2 Wheel Drive 4 Wheel Drive Condition:		
Exterior: Color: White Windows: ☑No Cracked Glass ☐ Cracked		
Additional Damage:		
Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No Impressions Emergency equip: None Has been removed & There are holes in the exterior There are no holes		
Interior: Color Black WCloth Vinyl Leather		
Damage to Seats: DIS TOYN		
Damage to Dash/Floor:		
		AM/FM AM/FM Cassette AM/FM CD
AC (Condition: Cold Unknown) No AC Air Bags: Driver's Side Dual		
Cruise Control Tilt Steering Remote Mirrors Climate Control		
Power: Steering Windows M		
Additional Equipment:		
Manufacturer Moo		
		Hitch: Type
Location of Asset:		
For more information contact: Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.		