

Rear Tire Condition	Finding: 6/32, 6/32
Alignment	Finding:
Steering/Suspension Components	Finding:
Rack & Pinion, Pump, Hos	ses & Finding:
Front Brake Lining/Calipe	rs Finding: 10mm
Rear Brake Lining/Caliper	s Finding: 10mm
✓ □ □ Brake Hydraulic System 8	Fluid Finding:
Emergency Brake Adjustr	nent Finding:
😳 \land 🗶 — Under Car Inspection	
Axle Shafts & Boots/U-Jo	nts Finding:
Condition of Front Struts/Shocks	Finding:
Condition of Rear Struts/Shocks	Finding:
Condition of Muffler	Finding:
Condition of Exhaust Pipe Hangers	s & Finding:
Engine or Transmission	Finding:

	Condition of Rear Diff. Fluid or Leaks	Finding:
© A X -	Underhood/Lights/Wipers	
	Condition of Belts (P/S, A/C or Alternator)	Finding:
	Condition of Trans Fluid	Finding:
	Condition of Coolant Sample	Finding:
	Condition of Radiator & Hose	Finding:
	Condition of Heater Hoses	Finding:
	Condition of Battery & Terminals	Finding:
	Condition of Battery Cables	Finding:
	Condition of Tune Up Components	Finding:
	Condition of Filters (air, fuel & pcv)	Finding:
	Condition of Engine oil	Finding:
	Headlights & Adjustment	Finding:
	Lights (brake, tail, turn signal, etc)	Finding:
	Condition of Wiper Blades	Finding:
© \land 🗙 –	Odometer	
	Factory Scheduled Maintenance	Finding:
	State Inspection	Finding:
	Other	Finding: