

Vehicle Inspection Form

Inventory ID:	Asset Number:	Fair Market Value:
Short Description: Year <u>Make Dodge</u> Model <u>Dirango</u>		
VIN:	Title: ☒ Clean Title ☐ Salvage Title ☐ No Title ☐ Court Documents Only ☐ SF97 Form ☐ Other	
Odometer: <u>287592</u> ☒ Miles ☐ Kilometers ☐ Hours	Odometer Accurate? ☒ Yes ☐ No ☐ Unknown	
Long Description:		
This Vehicle: ☐ Stolen ☒ Starts with a Boost & ☒ Runs/Drivable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only		
Engine Type: <u>4.7 L V</u> ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid		
Engine Condition: ☒ Runs ☒ Needs repair ☐ Is in unknown condition		
Repairs needed: <u>Driver side Exhaust leak</u>		
This vehicle was maintained every <u>5000</u> ☐ Days ☐ Hours ☒ Miles/Kilometers		
Date Removed from Service: <u>1-25</u> Maintenance Records: ☐ Available ☒ Not Available For Inspection		
Transmission: ☒ Automatic ☐ Manual ☐ Speed Condition: ☐ Operable ☐ Needs repair ☐ Is Unknown Condition		
Repairs Needed:		
Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: <u>good</u>		
Exterior: Color: <u>white</u> Windows: ☒ No Cracked Glass ☐ Cracked		
Minor: ☐ Dents ☒ Scratches ☒ Dings Tires Condition: <u>good</u> Tread: <u>1/32</u> #Flat <u>0</u> Hubcaps # <u>4</u>		
Major Damage to: <u>None</u>		
Additional Damage:		
Decals: ☒ None ☐ Have Been Sprayed or ☐ Have been Removed & ☐ Impressions Remain ☐ No Impressions		
Emergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes		
Interior: Color: <u>gray</u> ☒ Cloth ☐ Vinyl ☐ Leather		
Damage to Seats: <u>wear & tear belts But good</u>		
Damage to Dash/Floor: <u>cracked Dash Floor is good</u>		
Radio: ☒ Stock or ☐ Brand & Model: ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☒ AM/FM CD		
AC Condition: ☒ Cold ☐ Unknown ☐ No AC Air Bags: ☐ Driver's Side ☐ Dual		
☐ Cruise Control ☐ Tilt Steering ☐ Remote Mirrors ☐ Climate Control		
Power: ☐ Steering ☐ Windows ☐ Door Locks ☐ Seats		
Additional Equipment:		
Manufacturer: _____ Model: _____ Serial #: _____		
☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand: _____ ☐ Hitch Type: _____		
Location of Asset: _____		