

DO NOT SAVE THIS TAB AS A PDF

Confirm with the site contact if you are required to provide PPE: Hard Hat, Steel Toes, Safety Vest. . Etc..

When Scheduling the inspection, confirm that the seller has moved the unit to a location where you can take good photos without clutter or branding in the background.

This inspection requires a Tape Measure.

All Photos MUST Be taken Landscape (Camera turned on its side)

Equipment Information:

Unit No: 203411
Year: 1990
Make: Miller
Model:
VIN/SN: 1MLP34129LB314002

Equipment Condition:

Mechanical Condition: Fair - Functioning, but in need of repair

Interior Condition: Fair - Functioning, but in need of repair

Chassis:

GVWR: _____

Suspension: Spring

Tire Size: 11R24.5

Sliding Tandem Axle: Yes

Braking _____

Comments: _____

Deck

Hitch Type: Kingpin

Trailer Dimensions: Length: 45Ft

Width: 8Ft

Ramps (if equipped) _____

Specialized Equipment:

Type: _____ Details: _____

Type: _____ Details: _____

Notes: _____

Notes: _____