Boom Truck Condition Report:

			Equip	ment infor	mation:			
Unit No:	216729			Engine Information:				
Year:	2005			Year:	Year: 2005			
Make:	Freightliner			Make:	Make: Mercedes Benz			P:
Model:	CL 112			Model:	MBE-400	00		
VIN/SN:	1FVMF0CV65LV	/08104		SN:				
Miles/Hrs.:	294605			Fuel Type:	Diesel			
Equipment Condition:								
Mechar	nical Condition:	Good - Starts and operates; Some parts may require repair or replacement soon.						
Inte	erior Condition:	Fair - Interior is heavily worn.						
Exte	erior Condition:	Fair - Visible dents and scratches						
AC/H	eat Functional:							
	Leaks Present:	Not Seen	Engine D	isplacement:	12.8	Number of	Cylinders	6
Sleeper (if Applicable):		Length:		# of Bunks:	Aux Power Un		er Unit?	
Additio	nal Equipment:							
				Transmissic	n:			
	smission Make:	Freightliner						
Auto / Manual:		· ·						
Truck Moves FWD/REV:								
	Comments:							
Chassis:								
	Frame Rails:	Notes:						
	Suspension:	Spring				Notes:		
	Wheel Base:	9611118		in.				
Axle Weigh	t Ratings (LBS):	GVWR:	66,350	Front Axel:	14,000	Rear	(s): 42,350	
	Tire Size:	Front:	12R22.5			Rear(s): 11R2	•	
	Comments:	,						
				Flatbed				
	ed Dimensions: Length: 24'6"			ft.	Width:			
	or/Boom Make:	Length: 24'6" ft. Width: 8' ft. Conveyor/Boom Model:						
-	nveyor/Boom Is I			_				
		,						
Additio	onal Notes:							