## **Box Truck Condition Report:**

			Lquip		mation.				
Unit No:	231217		Engine Information:						
Year:	2013			Year:	2012				
Make:	Hino			Make:	Hino			HP:_	
Model:	268			Model:	J08-VC				
VIN/SN:	5PVNE8JT6D4S	55183		SN:					
Miles/Hrs.:				Fuel Type:	Diesel				
			Equi	ipment Con	dition:				
Mechar	ical Condition:	Poor - Will not start or operate and is in need of repair.							
Inte	rior Condition:	Fair - Inte	erior is hea	vily worn.					
Exte	rior Condition:	Fair - Visi	ble dents a	and scratches					
AC/H	eat Functional:	No							
	<b>Leaks Present:</b>	Not Seen	Engine D	isplacement:	7.6	Numb	er of Cylin	nders _	
Sleeper (if Applicable):		Length:		# of Bunks:	Aux Power Ur			it?	
Additio	nal Equipment:								
				Transmissio	n:				
	mission Make:								
Auto / Manual:						Number of	Speeds: _		
Truck Mo	oves FWD/REV:								
	Comments:								
Chassis:									
	Frame Rails:	Single				Notes:			
	Suspension:					Notes:			
	Wheel Base:			in.					
Axle Weigh	t Ratings (LBS):		25,950	Front Axel:	10,000		Rear(s):	19,000	
J	Tire Size:		11R22.5		,,	Rear(s):	11R22.5	,	
	Comments:					·			
				Flatbed					
	Bed Dimensions:	Length:	24	ft.	Width:	8 <b>f</b>	t.		
Conveyor/Boom Make:		Conveyor/Boom Model:							
Cor	nveyor/Boom Is I	Functional:		_		_			
Additio	nal Notes:								
<i></i>	'								