

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: _____

Other: Farm Tractor

Unit No: 232517

Year: 1996

Make: Ford

Model: 4630

VIN/SN: BD25314

Miles/Hrs.: 1873

Engine Information:

Year: 1996

Make: Ford

Model: 366144 2H28B

HP: _____

SN: _____

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

Hydraulics are Functional: Yes

Hydraulic Leaks Present: No

Unit Moves FWD/REV: Both

All Attachments Articulate: Yes

Notes: _____

Control Station Type: Canopy

AC/Heat: _____ AC/Heat working: _____

Additional Equipment: _____

Chassis:

Powertrain Type: _____

Propulsion Type: Wheel, Pneumatic

Track Condition: _____

Wheel Condition: Fair - Wheel condition shows heavy use and may require maintenance

Tire Size: _____

Front: LT245/75R15

Rear(s): 16.9-30

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: 2400QT Front End loader, 3 Point Hitch

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes: