

Trailer Condition Report:

Equipment Information:

Unit No: 279180
Year: 2017
Make: Clark
Model: CFBT
VIN/SN: 1CD2L5021HA011285

Equipment Condition:

Mechanical Condition: Poor - Non-Functional, Parts Trailer

Interior Condition: Poor - Non-Functional, Parts Trailer

Exterior Condition: Poor - Non-Functional, Parts Trailer

Chassis:

GVWR: 68,000

Suspension: Air

Tire Size:

Sliding Tandem Axle: No

Braking:

Comments:

Deck

Hitch Type: Kingpin

Dimensions: Length: 50

Width: 8

Ramps (if equipped)

Specialized Equipment:

Type:

Details:

Type:

Details:

Notes:

Notes: