Vehicle Condition Report:

Vehicle Information:

	Vehicle Type:	Box Truck					
	Other:						
Unit No:	307083		Engine Information:				
Year:	2006		Year:	2006			
Make:	Make: International		Make:	International			
Model:	del: DuraStar 4300		Model:	DT466			
VIN/SN:	1HTMMAAN46H3	01759	SN:				
Miles:	280640		Fuel Type:	Diesel			
		Ve	ehicle Cond	ition:			
Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.							
Interior Condition: Fair - Interior is heavily worn.							
Exterior Condition: Fair - Visible dents and scratches							
Condition Comments:							
Fngi	ne Displacement:	7.6 Liters. C r	ankshaft (V.	Inline, Boxer)		C	rlinders:
		Yes	armoriare (1)	Power Locks:	Yes		
Air Conditioner / Heat:		163	AC / Heat	Functional:	103		
7111 00	Transmission:	Manual	Number of Manual Speeds: 6				
Unit Moves FWD/REV:		Both			-p		
Four Wheel Drive (4x4):		No		Functional:			
Additional Equipment:		140		_			
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,							
	-						
Chassis:							
	Suspension:	Spring	Notes:				
	Wheelbase:	1 0	GVWR:		Front:		Rear(s):
Tire Size:		Front:	_		Rear:		
	Comments:	•			-		
	•						
Cargo / Passenger Vans							
Passel	nger van Seating:	Rows					
Cargo Van	Pay Dimensions:	. ممحداد	241	\A/: al=la -	O!	Uoiaht.	
_	Box Dimensions: Additional Notes:	Length:		Width: _	δ	Height:	
•	Auditional Notes:						