

Truck Tractor Condition Report:

Equipment Information:

Unit No: B10428
Year: 2007
Make: International
Model: 4300
VIN/SN: 1HTMMAAN97H361876
KM/Hrs.: 247485

Engine Information:
Year: 2007
Make: International
Model: DT466
SN:
Fuel Type: Diesel

Equipment Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

AC/Heat Functional:

Leaks Present: Not Seen Engine Displacement: 7.6 Number of Cylinders _____

Sleeper (if Applicable): Length: _____ # of Bunks: _____ Aux Power Unit? _____

Additional Equipment: _____

Transmission:

Transmission Make: _____

Auto / Manual: Automatic Number of Speeds: _____

Truck Moves FWD/REV: Both

Comments: flatbed is 20' x 8'

Chassis:

Frame Rails: _____ Notes: _____

Suspension: Spring Notes: _____

Wheel Base: 550 in. _____

Axle Weight Ratings (LBS): GVWR: 32,000 Front Axle: 11,000 Rear(s): 21,000

Tire Size: Front: 295/75R22.5 Rear(s): 11R22.5

Comments: _____

Specialized Equipment:

Type: _____ Details: _____

Type: _____ Details: _____

Notes: _____

Notes: _____