

Trailer Condition Report:

Equipment Information:

Unit No: B11518
Year: 2006
Make: Lufkin
Model: FL-II
VIN/SN: 1L01B452861160325

Miles/Hrs.:

Equipment Condition:

Mechanical Condition: Fair - Functioning, but in need of repair

Interior Condition: _____

Exterior Condition: Fair - Functioning, but in need of repair

Chassis:

GVWR: 80,000

Suspension: _____

Tire Size: 285/75R

Sliding Tandem Axle: _____

Braking: _____

Comments: Brakes are locked up, wood deck needs repair

Deck

Hitch Type: Kingpin

Dimensions: Length: 20'

Width: 102"

Ramps (if equipped) _____

Specialized Equipment:

Type: _____

Details: _____

Type: _____

Details: _____

Notes: _____

Notes: _____