

Vehicle Condition Report:

Vehicle Information:

Vehicle Type: Box Truck

Other: _____

Unit No: B13294

Engine Information:

Year: 2014

Year: 2014

Make: Freightliner

Make: Cummins

Model: M2 106

Model: ISB

VIN/SN: 3ALACXDT0EDFZ6029

SN: _____

Miles: 289184

Fuel Type: Diesel

Vehicle Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

Condition Comments: _____

Engine Displacement: 6.7 **Liters.** **Crankshaft (V, Inline, Boxer)** _____ **Cylinders:** 6

Power Windows: No **Power Locks:** No

Air Conditioner / Heat: Yes **AC / Heat Functional:** _____

Transmission: Automatic **Number of Manual Speeds:** _____

Unit Moves FWD/REV: Both

Four Wheel Drive (4x4): No **Functional:** _____

Additional Equipment: _____

Chassis:

Suspension: Air **Notes:** _____

Wheelbase: _____ **GVWR:** 33000 **Front:** 12000 **Rear(s):** 21000

Tire Size: _____ **Front:** 11R22.5 **Rear:** 11R22.5

Comments: _____

Cargo / Passenger Vans

Passenger Van Seating: _____ **Rows:** _____

Cargo Van Box Dimensions: _____ **Length:** 30' **Width:** 9' **Height:** _____

Additional Notes: _____