

Trailer Condition Report:

Equipment Information:

Unit No: B13569
Year: 1999
Make: Hyundai
Model: VI2280151FJPR
VIN/SN: 3H3V281C2XT034738

Miles/Hrs.:

Equipment Condition:

Mechanical Condition: Fair - Functioning, but in need of repair
Interior Condition: Fair - Functioning, but in need of repair
Exterior Condition: Fair - Functioning, but in need of repair

Chassis:

GVWR: 40,000
Tire Size: 295/75R22.5
Braking: _____
Comments: _____

Suspension: Air
Sliding Tandem Axle: _____

Deck

Hitch Type: Kingpin
Dimensions: Length: 28' Width: 8'
Ramps (if equipped) _____

Specialized Equipment:

Type: _____ Details: _____
Type: _____ Details: _____

Notes: _____

Notes: _____