

Trailer Condition Report:

Equipment Information:

Unit No: B76061

Year: 2001

Make: Great Dane

Model: _____

VIN/SN: 1GRAA06221B110523

Miles/Hrs.: _____

Equipment Condition:

Mechanical Condition: Good - Some Parts May Require Repair or Replacement Soon

Interior Condition: Good - Some Parts May Require Repair or Replacement Soon

Exterior Condition: Good - Some Parts May Require Repair or Replacement Soon

Chassis:

GVWR: 68,000

Suspension: Air

Tire Size: 295/80R22.5

Sliding Tandem Axle: _____

Braking: Air

Comments: 53' X 8'

Deck

Hitch Type: Kingpin

Dimensions: _____ Length: 53' Width: 8'

Ramps (if equipped) _____

Specialized Equipment:

Type: _____ Details: _____

Type: _____ Details: _____

Notes: _____

Notes: _____