

Truck Tractor Condition Report:

Equipment Information:

Unit No: B78919
Year: 2014
Make: Kenworth
Model: T370
VIN/SN: 2NKHHJ7X8EM418173
KM/Hrs.: 217986/9300

Engine Information:
Year: 2014
Make: Paccar
Model: PX-9
SN:
HP:
Fuel Type: Diesel

Equipment Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.
Interior Condition: Good - Damage is limited to normal wear and minor scratches.
Exterior Condition: Good - Minor dings and scratches
AC/Heat Functional: Yes
Leaks Present: Not Seen Engine Displacement: 8.9 Number of Cylinders: 6
Sleeper (if Applicable): Length: # of Bunks: Aux Power Unit?
Additional Equipment: _____

Transmission:

Transmission Make: _____
Auto / Manual: Automatic Number of Speeds: _____
Truck Moves FWD/REV: Both
Comments: _____

Chassis:

Frame Rails: _____ Notes: _____
Suspension: Spring Notes: _____
Wheel Base: in. _____
Axe Weight Ratings (LBS): GVWR: 31,300 Front Axel: 11,020 Rear(s): 20,280
Tire Size: Front: 275/70R22.5 Rear(s): 275/70R22.5
Comments: _____

Specialized Equipment:

Type: _____ Details: _____
Type: _____ Details: _____
Notes: _____
Notes: _____