

Trailer Condition Report:

Equipment Information:

Unit No: B90617Z
Year: 1997
Make: Lynnwoord
Model:
VIN/SN: LTE2972080

Equipment Condition:

Mechanical Condition: Fair - Functioning, but in need of repair

Physical Condition: Fair - Functioning, but in need of repair

Chassis:

GVWR: _____

Suspension: _____

Tire Size: _____

Sliding Tandem Axle: _____

Braking: _____

Comments: _____

Deck

Hitch Type: _____

Dimensions: Length: 38Ft Width: 6Ft

Ramps (if equipped) _____

Specialized Equipment:

Type: _____ Details: _____

Type: _____ Details: _____

Notes: 38Ft is the length of the trailer. The Deck is 20Ft x 6Ft

Notes: _____