

Fork Lift Condition Report:

Forklift Information

Unit No: FUL3177
Year: _____
Make: Hyundai
Model: 35D-9
VIN/SN: HHKHFV25P0000012

Miles/Hrs.: 11279/7247

Engine Information:
Year: _____
Make: _____
Model: _____ HP: _____
SN: _____

Fuel Type: Diesel

Forklift Condition

Mechanical Condition: Fair - Starts and operates but some parts require repair or replacement.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

Control Station:

Steering Control Operational: Yes Notes: _____
Control Station Type: Canopy
AC/Heat (If enclosed Cab): No AC/Heat Functional: _____
Additional Equipment: _____

Hydraulics:

Hydraulics are Functional: Yes Hydraulic Leaks Present: Yes
Unit Moves FWD/REV: Both
All Attachments Articulate Yes Notes: _____
Comments: side shift hydraulic leak

Undercarriage:

Powertrain Type: 2WD Drivetrain is functional: Yes
Tire Type: Solid Pneumatic Non-Marking? _____
Comments: _____

Mast:

Mast Type: 3-Stage
Max Lift Height: 185 In. Lowered Mast Height: _____ In.
Fork Length: 48 In.
Fork Positioner: No Notes: _____
Side Shift: Yes Notes: _____
Scales: No Notes: _____
Other Attachments: No Notes: _____