

Trailer Condition Report:

Equipment Information:

Unit No: NL1488

Year: 2016

Make: Dorsey

Model: _____

VIN/SN: 5JYFB4522GE087582

Miles/Hrs.: _____

Equipment Condition:

Mechanical Condition: Good - Some Parts May Require Repair or Replacement Soon

Interior Condition: Fair - Functioning, but in need of repair

Exterior Condition: Fair - Functioning, but in need of repair

Chassis:

GVWR: _____

Suspension: Air

Tire Size: _____

Sliding Tandem Axle: _____

Braking: _____

Comments: Can't read VIN tag

Deck

Hitch Type: Kingpin

Dimensions: _____ Length: 45' Width: 102"

Ramps (if equipped) _____

Specialized Equipment:

Type: _____ Details: _____

Type: _____ Details: _____

Notes: _____

Notes: _____