

Trailer Condition Report:

Equipment Information:

Unit No: NL1547
Year: 2015
Make: Dorsey
Model: _____
VIN/SN: 5JYFB4527FE086538

Equipment Condition:

Mechanical Condition: Good - Some Parts May Require Repair or Replacement Soon
Interior Condition: Good - Some Parts May Require Repair or Replacement Soon
Exterior Condition: Good - Some Parts May Require Repair or Replacement Soon

Chassis:

GVWR: 80,000 Suspension: Air
Tire Size: _____ Sliding Tandem Axle: _____
Braking: _____
Comments: _____

Deck

Hitch Type: Kingpin
Dimensions: _____ Length: 45' Width: 8'
Ramps (if equipped) _____

Specialized Equipment:

Type: _____ Details: _____
Type: _____ Details: _____

Notes: _____
Notes: _____