

Boom Truck Condition Report:

Equipment Information:

Unit No: NL1768
Year: 2005
Make: Kenworth
Model: T300
VIN/SN: 2NKMHD7X05M083264

Miles/Hrs.: 597562/16006

Engine Information:
Year: _____
Make: CAT
Model: C7
SN: _____
Fuel Type: Diesel

Starts and Runs: **No**

Equipment Condition:

Mechanical Condition: Poor - Will not start or operate and is in need of repair.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

AC/Heat Functional: _____

Leaks Present: Not Seen Engine Displacement: 7.2 Number of Cylinders 6

Air Lift 3rd Axle in front of drive wheels _____

Air Lift Tag Axle behind drive wheels

Additional Equipment: Flatbed Truck

Transmission:

Transmission Make: Eaton Fuller

Auto / Manual: Manual Number of Speeds: 6

Truck Moves FWD/REV: Neither

Comments: _____

Chassis:

Frame Rails: _____ Notes: _____

Suspension: Air Notes: _____

Wheel Base: _____ in. _____

Axle Weight Ratings (LBS): GVWR: 33,000 Front Axle: 12,000 Rear(s): 21,000

Tire Size: Front: 11R22.5 Rear(s): 11R22.5

Comments: _____

Flatbed

Bed Dimensions: Length: 22 Ft. Width: 8 Ft.

Turntable Make: _____ Turntable Model: _____

Conveyor/Boom Make: _____ Conveyor/Boom Model: _____

Conveyor/Boom Is Functional: _____

Additional Notes: _____