

# Truck Tractor Condition Report:

## Equipment Information:

Unit No: PB236416  
Year: 2016  
Make: Peterbilt  
Model: 337      Axle: Single  
VIN/SN: 2XP2AJ7X4GM275882  
KM/Hrs.: 253844

Engine Information: Starts and Runs: Yes  
Year: 2016  
Make: PACCAR  
Model: PX-9      HP:  
SN: 73848946  
Fuel Type: Diesel

## Equipment Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Good - Minor dings and scratches

AC/Heat Functional: Yes

Leaks Present: Not Seen      Engine Displacement: 8.9      Number of Cylinders: 6

Sleeper (if Applicable): Length:      # of Bunks:      Aux Power Unit? \_\_\_\_\_

Additional Equipment: \_\_\_\_\_

## Transmission:

Transmission Make: Allison

Auto / Manual: Automatic      Number of Speeds: \_\_\_\_\_

Truck Moves FWD/REV: Both

Comments: \_\_\_\_\_

## Chassis:

Frame Rails:      Notes: \_\_\_\_\_

Suspension: Spring      Notes: \_\_\_\_\_

Wheel Base:      in.      \_\_\_\_\_

Axle Weight Ratings (LBS):      GVWR: 33,000      Front Axle: 12,000      Rear(s): 21,000

Tire Size:      Front: 11R22.5      Rear(s): 11R22.5

Comments: \_\_\_\_\_

## Specialized Equipment:

Type:      Details: \_\_\_\_\_

Type:      Details: \_\_\_\_\_

Notes: \_\_\_\_\_

Notes: \_\_\_\_\_