

Trailer Condition Report:

Equipment Information:

Unit No:	PB236742
Year:	2008
Make:	Clark
Model:	CFPT2008
VIN/SN:	1CD2L45258A009509

Equipment Condition:

Mechanical Condition: Fair - Functioning, but in need of repair

Physical Condition: Fair - Functioning, but in need of repair

Chassis:

GVWR:	64,000	Suspension:	Spring
Tire Size:	295/75R22.5	Sliding Tandem Axle:	
Braking:			
Comments:	Some wood rot, tool box broken and trailer showing signs of heavy use		

Deck

Hitch Type:	Kingpin	
Dimensions:	Length: 45'	Width: 92"
Ramps (if equipped)		

Specialized Equipment:

Type: _____	Details: _____
Type: _____	Details: _____

Notes: _____

Notes: _____