

1998 MITSUBISHI FD40D | AF19B00307



Specifications

Engine Hours	12,823	Engine Make	Mitsubishi
Engine Model	S6S diesel	Engine Serial	32831-2030
Engine HP	80	Fuel Type	Diesel
Fuel Tanks	1 Steel	Fuel Capacity	17
Trans Make	Mitsubishi	Trans Type	Auto
Trans Model	Hydraulic Powershift	Axle Type	Single
Axle F Capacity	12,000	Axle R Capacity	6,000
GVWR	18,000	Frame Type	C (Double)
Wheelbase	65	Brake Type	Hydraulic
Air Cond	No	Interior Color	Black
Int Type	Vinyl	Exterior Color	Green/Teal

Tires, Wheels & Brakes - Front Axle

Left	Right
Tires/Wheels	Tires/Wheels
Fair	Fair
300x15 SOLID	300x15 SOLID
Virgin	Virgin
32/32	32/32
Steel	Steel
Brakes	Brakes
32/32	32/32

Tires, Wheels & Brakes - Rear Axles

Left	Right
Tires/Wheels	Tires/Wheels
Fair	Fair
7.00x12 SOLID	7.00x12 SOLID
32/32	32/32
Steel	Steel
Brakes	Brakes
0/32	0/32

Observations

Keys Present?	1 Sets	Oil Leaks?	Yes
Oil Milky?	No	Water Leaks?	No
Oil in Coolant?	No	Clutch Play?	No
Starts?	Yes	Drives?	Yes
Cracked/Chipped Glass?		Lights Works?	No
Wipers Works?	NA	Guages Works?	Yes
Air Horn Works?		City Horn Works?	
Active Fault Codes	NA		


General Observation Notes

Engine shows minor oil seepage at hose connection and filter housing. One exterior light inoperative. Solid tires exhibit normal chunking consistent with industrial wear.

Deficiencies

Issue #	Check	Comment	Photo
D1	Cooling Fan Blades Missing	Radiator/cooling fan has missing plastic blades; reduced airflow and potential imbalance noted.	
D2	Inoperative Light	One exterior light not functioning at time of inspection.	

Photos



Videos

- Video 1
- Video 2
- Video 3

This report reflects the vehicle's condition at the time of inspection only. No warranty is made as to mechanical reliability, safety, or future performance.