

# Flatbed Truck Condition Report:

## Equipment Information:

Unit No: PB270684  
Year: 2014  
Make: Peterbilt  
Model: 337  
VIN/SN: 2NP2HJ7X9EM246509

Miles/Hrs.: 383876

## Engine Information:

Year: 2014  
Make: PACCAR  
Model: PX-9  
SN:

Fuel Type: Diesel

## Equipment Condition:

Mechanical Condition: Poor - Will not start or operate and is in need of repair.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

AC/Heat Functional:

Leaks Present: Not Seen Engine Displacement: 8.9 Number of Cylinders 6

Sleeper (if Applicable): Length: # of Bunks: Aux Power Unit?

Additional Equipment:

## Transmission:

Transmission Make: Allison

Auto / Manual: Automatic Number of Speeds:

Truck Moves FWD/REV: Both

Comments:

## Chassis:

Frame Rails: Notes:

Suspension: Spring Notes:

Wheel Base: in.

Axle Weight Ratings (LBS): GVWR: Front Axle: Rear(s):

Tire Size: Front: 11R22.5 Rear(s): 11R22.5

Comments:

## Flatbed

Bed Dimensions: Length: 20 ft. Width: 8 ft.

Conveyor/Boom Make: Conveyor/Boom Model:

Conveyor/Boom Is Functional:

Additional Notes: