

# Vehicle Condition Report:

## Vehicle Information:

Vehicle Type: Box Truck

Other: \_\_\_\_\_

Unit No: PB270857

Engine Information:

Year: 2016

Year: \_\_\_\_\_

Make: Peterbilt

Make: PACCAR

Model: 337

Model: \_\_\_\_\_

VIN/SN: 2NP2HM6X3GM270987

SN: \_\_\_\_\_

Miles: 400348

Fuel Type: Diesel

## Vehicle Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

Condition Comments: Box has a hole in the roof Passenger side, behind the cab.

Engine Displacement: 6.7 Liters. Crankshaft (V, Inline, Boxer) V Cylinders: 6

Power Windows: Yes

Power Locks: Yes

Air Conditioner / Heat: Yes

AC / Heat Functional: Could not confirm

Transmission: Automatic

Number of Manual Speeds: \_\_\_\_\_

Unit Moves FWD/REV: Both

Four Wheel Drive (4x4): No

Functional: N/A

Additional Equipment: \_\_\_\_\_

## Chassis:

Suspension: Spring

Notes: \_\_\_\_\_

Wheelbase: \_\_\_\_\_

GVWR: 26000

Front: 10000 Rear(s): \_\_\_\_\_

Tire Size: Front: 295/75R22.5

Rear: 295/75R22.5

Comments: \_\_\_\_\_

## Cargo / Passenger Vans

Passenger Van Seating: \_\_\_\_\_ Rows \_\_\_\_\_

Cargo Van Box Dimensions:

Length: 12Ft

Width: 93In

Height: \_\_\_\_\_

Additional Notes: \_\_\_\_\_