

Flatbed Condition Report:

Equipment Information:

Unit No:	PB271141	Engine Information:	Starts and Runs:	Yes			
Year:	2014	Year:	2014				
Make:	Peterbilt	Make:	Cummins				
Model:	365	Axle:	Tandem	Model:	ISX	HP:	
VIN/SN:	1NPSX7EX6ED249303	SN:					
KM/Hrs.:	348391	Fuel Type:	Diesel				

Equipment Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Good - Damage is limited to normal wear and minor scratches.

Exterior Condition: Good - Minor dings and scratches

AC/Heat Functional: Yes

Leaks Present: Not Seen

Engine Displacement: _____ **Number of Cylinders:** _____

Sleeper (if Applicable): Length: _____ # of Bunks: _____ **Aux Power Unit?** _____

Additional Equipment: _____

Transmission:

Transmission Make: Eaton Fuller

Auto / Manual: Manual **Number of Speeds:** 10

Truck Moves FWD/REV: Both

Comments: _____

Chassis:

Frame Rails: _____ **Notes:** _____

Suspension: Spring **Notes:** _____

Wheel Base: _____ in.

Axle Weight Ratings (LBS): GVWR: 78,240 **Front Axel:** 32,240 **Rear(s):** 46,000

Tire Size: Front: 385/65R22.5 **Rear(s):** 385/65R22.5

Comments: _____

Specialized Equipment:

Type: _____ **Details:** _____

Type: _____ **Details:** _____

Notes: _____

Notes: _____