

2016 PETERBILT 337 | 2XP2AJ7X8GM348770



Specifications

OD Miles	226,546	ECM Miles	49,719
Engine Hours	9,875	Engine Make	Paccar
Engine Model	PX-9	Engine Serial	73864810
Engine HP	330	Fuel Type	Diesel
Fuel Tanks	1 Alum	Fuel Capacity	95
Exhaust	Single	Breathers	Single
Trans Make	Allison	Trans Type	Auto
Trans Model	3000 HS	Trans Speed	6
Over Drive	Yes	Cruise Control	Yes
Wet Line	No	Power Steering	Yes
Axle Type	Single	Axle F Capacity	12,000
Axle R Capacity	21,000	GVWR	33,000
Frame Type	Steel	Suspension	Air Ride
Wheelbase	155	Brake Type	Air
5th Wheel	Stationary	Engine Brake	No
Air Cond	Yes	Interior Color	Gray
Exterior Color	White	Heated Mirrors	No
Fairings	None	Visor	Yes
Power Mirrors	Yes	High Back Seats	Dual
Passenger Seat	Stationary	Dual Bunks	No
APU	No	Bumper	Chrome
Collision Avoidance	No		

Tires, Wheels & Brakes - Front Axle

Left

Tires/Wheels
Good
11R22.5
Virgin
15/32
Aluminum

Brakes
covered

Right

Tires/Wheels
Good
11R22.5
Virgin
15/32
Aluminum

Brakes
covered

Tires, Wheels & Brakes - Rear Axles

Left Outer

Tires/Wheels
Good
11R22.5
Retread
14/32
Aluminum

Brakes
covered

Left Inner

Tires/Wheels
Good
11R22.5
Retread
18/32
Aluminum

Brakes
covered

Right Inner

Tires/Wheels
Good
11R22.5
Retread
16/32
Aluminum

Brakes
covered

Right Outer

Tires/Wheels
Good
11R22.5
Retread
16/32
Aluminum

Brakes
covered

Observations

Keys Present?	1 Sets	Oil Leaks?	No
Oil Milky?	No	Water Leaks?	No
Oil in Coolant?	No	Clutch Play?	Yes
Starts?	Yes	Drives?	Yes
Cracked/Chipped Glass?	No	Lights Works?	Yes
Wipers Works?	Yes	Guages Works?	Yes
Air Horn Works?	Yes	City Horn Works?	Yes
Active Fault Codes	Yes		

General Observation Notes

Deficiencies

Issue #	Check	Comment	Photo
D1	Tires	Drive axle driver outside has nail on tire	

Photos



Videos

Video 1

Files

2XP2AJ7X8GM348770_2026_01_12T09_21_52_pdf

This report reflects the vehicle's condition at the time of inspection only. No warranty is made as to mechanical reliability, safety, or future performance.