## **Truck Tractor Condition Report:**

			Equipment infor				
Unit No: PB2	272804			Engine Information:			
<b>Year:</b> 200	04		Year:	2004			
Make: Fre	Freightliner		Make:	Mercedes Benz			
	M2 106		Model:	MBE-900	HP:		
VIN/SN: 1F\	VACWCT04H	M37853	SN:				
KM/Hrs.:			Fuel Type:	Diesel			
			<b>Equipment Con</b>	dition:			
Mechanical	Condition:	Poor - Will	not start or operate and				
Interior	Condition:	Fair - Interi	or is heavily worn.	·			
Exterior	Condition:	Fair - Visibl	e dents and scratches				
AC/Heat	Functional:	No					
Leaks Present:		Not Seen Engine Displacement:		6.4 <b>Number of Cylinders</b> 6		6	
Sleeper (if Applicable):		Length:	# of Bunks:	Au	Aux Power Unit?		
Additional E	Equipment:						
	• •						
			Transmissic	n:			
Transmis	smission Make: Freightliner		ier				
Auto	o / Manual:	Manual		Number of Speeds: 6			
Truck Moves	FWD/REV:	Neither					
(	Comments:	truck has	been sitting for a couple	years, no clutch			
			Chassis:				
F	romo Doile.		Clid5515.	Notes			
Frame Rails:				Notes			
	uspension: Vheel Base:		·	Notes	-		
			in. 25,500 Front Axel:	8 000	Poor/s\.	17.500	
Axle Weight Ra	Tire Size:			8,000	Rear(s):	17,500	
		Front:	275/80R22.5	Rear(s)	: 275/80R22.5		
'	Comments:						
			Cracialized Faui	n m a m tu			
			Specialized Equi	pment:			
ype:			Details:				
ype:			Details:				
lotos							
lotes: lotes:							