

Trailer Condition Report:

Equipment Information:

Unit No: PB273537

Year: 2014

Make: Precision

Model: _____

VIN/SN: 1P9SR5123EF554137

Miles/Hrs.: _____

Equipment Condition:

Mechanical Condition: Fair - Functioning, but in need of repair

Interior Condition: Fair - Functioning, but in need of repair

Exterior Condition: Fair - Functioning, but in need of repair

Chassis:

GVWR: 64,000

Suspension: Spring

Tire Size: 255/70R22.5

Sliding Tandem Axle: _____

Braking: Air

Comments: unit has heavy corrosion, they only use around the yard not road worthy

Deck

Hitch Type: Kingpin

Dimensions: _____ Length: 51' Width: 101"

Ramps (if equipped) _____

Specialized Equipment:

Type: _____ Details: _____

Type: _____ Details: _____

Notes: _____

Notes: _____