

Vehicle Condition Report:

Vehicle Information:

Vehicle Type: Box Truck

Other: _____

Unit No: PB274208

Year: 2004

Make: Sterling

Model: Acterra

VIN/SN: 2FZACFCT14AM55599

Miles: 318592

Engine Information:

Year: 2004

Make: Mercedes Benz

Model: MBE-900

SN: _____

Fuel Type: Diesel

Vehicle Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

Condition Comments: _____

Engine Displacement: 6.4 Liters. Crankshaft (V, Inline, Boxer) _____ Cylinders: 6

Power Windows: No

Power Locks: No

Air Conditioner / Heat: Yes

AC / Heat Functional: _____

Transmission: Manual

Number of Manual Speeds: 6

Unit Moves FWD/REV: Both

Four Wheel Drive (4x4): No

Functional: _____

Additional Equipment: _____

Chassis:

Suspension: Spring

Notes: _____

Wheelbase: _____

GVWR: 25500

Front: 8000

Rear(s): 17500

Tire Size: _____

Front: 255/80R22.5

Rear: 255/80R22.5

Comments: _____

Cargo / Passenger Vans

Passenger Van Seating: _____ Rows _____

Cargo Van Box Dimensions:

Length: 24'

Width: 7'8"

Height: _____

Additional Notes: _____