

Truck Tractor Condition Report:

Equipment Information:

| | | | | |
|----------|-------------------|---------------------|------------------|-----|
| Unit No: | RPM1002 | Engine Information: | Starts and Runs: | Yes |
| Year: | 2006 | Year: | 2005 | |
| Make: | Freightliner | Make: | Mercedes Benz | |
| Model: | Columbia | Axle: | Tandem | |
| VIN/SN: | 1FUJA6CV86LW29629 | Model: | MBE4000 | HP: |
| KM/Hrs.: | 96484 | SN: | | |
| | | Fuel Type: | Diesel | |

Equipment Condition:

| | | | |
|--------------------------|--|----------------------|------|
| Mechanical Condition: | Good - Starts and operates; Some parts may require repair or replacement soon. | | |
| Interior Condition: | Fair - Interior is heavily worn. | | |
| Exterior Condition: | Fair - Visible dents and scratches | | |
| AC/Heat Functional: | Yes | | |
| Leaks Present: | Not Seen | Engine Displacement: | 12.8 |
| Sleeper (if Applicable): | Length: | # of Bunks: | |
| Additional Equipment: | | Number of Cylinders | 6 |
| | | Aux Power Unit? | |

Transmission:

| | | | |
|----------------------|--------|-------------------|----|
| Transmission Make: | Eaton | | |
| Auto / Manual: | Manual | Number of Speeds: | 10 |
| Truck Moves FWD/REV: | Both | | |
| Comments: | | | |

Chassis:

| | | | | | | |
|----------------------------|------------|--------|-------------|----------|-------------|--------|
| Frame Rails: | Single | Notes: | | | | |
| Suspension: | Air | Notes: | | | | |
| Wheel Base: | | in. | | | | |
| Axle Weight Ratings (LBS): | GVWR: | 52,000 | Front Axel: | 12,000 | Rear(s): | 40,000 |
| | Tire Size: | Front: | 285/75R22.5 | Rear(s): | 285/75R22.5 | |
| Comments: | | | | | | |

Specialized Equipment:

| | | | |
|--------|--|----------|--|
| Type: | | Details: | |
| Type: | | Details: | |
| Notes: | | | |
| Notes: | | | |