

# Truck Tractor Condition Report:

## Equipment Information:

Unit No: RPM1020  
Year: 2018  
Make: Freightliner  
Model: M2      Axle: Tandem  
VIN/SN: 3ALHCFE7JDJX8402  
KM/Hrs.: 180457

Engine Information: Starts and Runs: Yes  
Year: 2018  
Make: Cummins  
Model: L9      HP:  
SN:      Fuel Type: Diesel

## Equipment Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Good - Damage is limited to normal wear and minor scratches.

Exterior Condition: Good - Minor dings and scratches

AC/Heat Functional: Yes

Leaks Present: Not Seen      Engine Displacement: 9      Number of Cylinders 6

Sleeper (if Applicable): Length:      # of Bunks:      Aux Power Unit?

Additional Equipment: \_\_\_\_\_

## Transmission:

Transmission Make: Allison

Auto / Manual: Automatic      Number of Speeds: \_\_\_\_\_

Truck Moves FWD/REV: Both

Comments: \_\_\_\_\_

## Chassis:

Frame Rails:      Notes: \_\_\_\_\_

Suspension: Air      Notes: \_\_\_\_\_

Wheel Base:      in.      \_\_\_\_\_

Axle Weight Ratings (LBS):      GVWR: 52,000      Front Axle: 12,000      Rear(s): 40,000

Tire Size:      Front: 295/75R22.5      Rear(s): 295/75R22.5

Comments: \_\_\_\_\_

## Specialized Equipment:

Type:      Details: \_\_\_\_\_

Type:      Details: \_\_\_\_\_

Notes:      Deck Dimensions: 22Ft x 8Ft

Notes: \_\_\_\_\_