

Vehicle Condition Report:

Vehicle Information:

Vehicle Type: Box Truck

Other: _____

Unit No: TWP1054

Year: 2007

Make: Sterling

Model: Acterra

VIN/SN: 2FZACFC SX7AZ22417

Miles: 391018

Engine Information:

Year: 2007

Make: Mercedes

Model: MBE-900

SN: _____

Fuel Type: Diesel

Vehicle Condition:

Mechanical Condition: Fair - Starts and operates but some parts require repair or replacement.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

Condition Comments: liftgate has a leak that makes it lose power, unit has no vin sticker

Engine Displacement: 6.4 Liters. Crankshaft (V, Inline, Boxer) _____ Cylinders: 6

Power Windows: No

Power Locks: No

Air Conditioner / Heat: Could not confirm

AC / Heat Functional: _____

Transmission: Automatic

Number of Manual Speeds: _____

Unit Moves FWD/REV: Both

Four Wheel Drive (4x4): No

Functional: _____

Additional Equipment: _____

Chassis:

Suspension: Spring

Notes: _____

Wheelbase: _____

GVWR: _____

Front: _____

Rear(s): _____

Tire Size: _____

Front: 11R22.5

Rear: 11R22.5

Comments: _____

Cargo / Passenger Vans

Passenger Van Seating: _____ Rows _____

Cargo Van Box Dimensions:

Length: 22'

Width: 8'

Height: _____

Additional Notes: _____