Trailer Condition Report:

| | Lquipi | ment imormatio | 111. | |
|-------------------|-------------------------------|----------------------|--------|------|
| Unit No: WYO1076 | 5 | | | |
| Year: 2005 | | | | |
| Make: | | | | |
| Model: | | | | |
| VIN/SN: 171717D | | | | |
| Miles/Hrs.: | | | | |
| | Equi | pment Condition | : | |
| Mechanical Cond | ition: Fair - Functioning, bu | ut in need of repair | | |
| Interior Cond | ition: Fair - Functioning, bu | ut in need of repair | | |
| Exterior Cond | ition: Fair - Functioning, bu | ut in need of repair | | |
| | | Chassis: | | |
| G ¹ | VWR: | Suspension: | | |
| Tire | Size: | Sliding Tandem Axle: | | |
| Bra | aking: | | | |
| Comm | ents: | | | |
| | | Deck | | |
| Hitch Ty | /pe: | | | |
| Dimensio | ons: Length: | 20'10" | Width: | 7'8" |
| Ramps (if equipp | oed) | | | |
| | | | | |
| | Specia | alized Equipmen | t: | |
| Туре: | | Details: | | |
| Туре: | | Details: | | |
| | | | | |
| Notes: | | | | |
| Notes: | | | | |
| | | | | |