

DO NOT SAVE THIS TAB AS A PDF

Confirm with the site contact if you are required to provide PPE: Hard Hat, Steel Toes, Safety Vest. . Etc..

When Scheduling the inspection, confirm that the seller has moved the unit to a location where you can take good photos without clutter or branding in the background.

This inspection requires a Tape Measure.

All Photos MUST Be taken Landscape (Camera turned on its side)

Asset Information:

Equipment Type: Loader

Other: _____

Unit No: 12970 / 794251

Engine Information:

Year: 2003

Year: _____

Make: Caterpillar

Make: _____

Model: 992G

Model: _____

HP: _____

VIN/SN: ADZ00468

SN: _____

Miles/Hrs.: _____

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Poor - Will not start or operate and is in need of repair.

Interior Condition: Poor - Interior has severe damage and/or tears beyond normal wear.

Exterior Condition: Poor - Major body damage.

Hydraulics are Functional: Could not confirm

Hydraulic Leaks Present: _____

Unit Moves FWD/REV: Neither

All Attachments Articulate: Could not confirm

Notes: _____

Control Station Type: Enclosed Cab

AC/Heat: Yes

AC/Heat working: Could not confirm

Additional Equipment: _____

Chassis:

Powertrain Type: 4WD

Propulsion Type: Wheel, Pneumatic - All Terrain

Track Condition: _____

Wheel Condition: Poor - Wheel Condition is damaged and will need to be replace

Tire Size: _____

Front: _____

Rear(s): _____

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: _____

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes: