Heavy Equipment Condition Report:

		Lillorillat	1011.		
Equipment Type: _	Loader				
Other: _					
Unit No: 10185 / 715444			E	Engine Information:	
Year: 1999		Year:			
Make: Caterpillar		Make:	Caterpilla	ar	
Model: 980G		Model:	3406		HP:
VIN/SN: 2KR03309		SN:			
Miles/Hrs.:		Fuel Type:	Diesel		
Asset Condition:					
Mechanical Condition:	Poor - Will not start o	r operate and	d is in need	d of repair.	
Interior Condition:	Fair - Interior is heavil	ly worn.			
Exterior Condition:	Fair - Visible dents an	d scratches			
Hydraulics are Functional:	Could not confirm	Hydra	aulic Leak	s Present:	
Unit Moves FWD/REV:	Neither				
All Attachments Articulate	Could not confirm	Notes:			
Control Station Type:	Enclosed Cab	AC/Heat:	Yes	AC/Heat working:	Could not confirm
Additional Equipment: _					
Chassis:					
Powertrain Type:	4WD				
Propulsion Type:	Wheel, Pneumatic - All Terrain				
Track Condition:					
Wheel Condition:	Fair - Wheel condition shows heavy use and may require maintenance				
Tire Size:	Front:			Rear(s):	
	At	ttachment	S		
Are there additional attachme	ents that are not curr	ently conne	cted to th	nis asset?	
Describe:					
Туре:		Details:			
Туре:	Details:				
Additional Notes:					