

DO NOT SAVE THIS TAB AS A PDF

Confirm with the site contact if you are required to provide PPE: Hard Hat, Steel Toes, Safety Vest. . Etc..

When Scheduling the inspection, confirm that the seller has moved the unit to a location where you can take good photos without clutter or branding in the background.

This inspection requires a Tape Measure.

All Photos MUST Be taken Landscape (Camera turned on its side)

Asset Information:

Equipment Type: Dozer

Other: _____

Unit No: 12555 / 789540

Engine Information:

Year: 1980

Year: _____

Make: Caterpillar

Make: Caterpillar

Model: 824C

Model: 3406

HP: _____

VIN/SN: 85X00584

SN: _____

Miles/Hrs.: _____

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Poor - Will not start or operate and is in need of repair.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

Hydraulics are Functional: Could not confirm

Hydraulic Leaks Present:

Unit Moves FWD/REV: Neither

All Attachments Articulate: Could not confirm

Notes: _____

Control Station Type: Enclosed Cab

AC/Heat: Yes

AC/Heat working: Could not confirm

Additional Equipment: _____

Chassis:

Powertrain Type: 4WD

Propulsion Type: Wheel, Pneumatic - All Terrain

Track Condition:

Wheel Condition: Fair - Wheel condition shows heavy use and may require maintenance

Tire Size:

Front: _____

Rear(s): _____

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: _____

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes: